
Service Bulletin: SB 50


DATE: March 2, 1993

GAME: Whitewater

SUBJECT: Intermittent or weak action from ball popper assembly A-15769

CAUSE: Rubber Grommet missing or installed incorrectly on ball popper assembly

We have had a few customers reporting that the rubber grommet (part #23-6420) on the ball popper assembly of "**Whitewater**" pinballs have been missing. See the diagram below for the location of the grommet. Please check your game and install a new grommet if needed.



Thank you,
WMS GAMES Parts & Service INC.
