

This notice applies to all Lost World, House of Dead 2, Brave Firefighter, and Confidential Mission Games using Sega IR Tracking System.

Problem: Led Bds around perimeter of screen burn out due to gun problems.

Solution: Install a 500mamp (1/2 amp) Fast Blow Fuse on the 12 volt input to the IC Bd Gun Sense. See drawing below.

(Example using an 838-13143-01)

