



Note: This Index is sorted with the latest bulletin at the top as in the binder. Hand write in space provided for new bulletins.

SPI SERVICE BULLETIN UPDATED INDEX 04 03 02 01 00 99 98 97

SB N°	DATE	GAME NAME(S)	SUBJECT OF BULLETIN
			
			
			
			
			
			
			
			
147	JAN 19, 2004	The Lord of the Rings™	Diverter Gate Adjustment Procedure
146	DEC 18, 2003	The Lord of the Rings™	FYI: Tower Eject Learning Mode
145	DEC 09, 2003	Terminator® 3	Auto Launch Diode Harness Installation...
144	DEC 09, 2003	The Lord of the Rings™	Spanish Display & Speech Available
143	OCT 22, 2003	Terminator® 3	Software Update / Match Feature
142	AUG 22, 2003	Terminator® 3	Auto Launch Wire(s) or Coil Lug(s) Break Off
141	AUG 13, 2003	Terminator® 3	Shooter Lane Switch Actuator Adjustment
140	JULY 24, 2003	Terminator® 3	Software Update v2.04 or Higher Eliminates
139	MAY 16, 2003	Monopoly®	F21 Fuse Blows Intermittently, System Checks OK
138	MAR 21, 2003	The Simpsons™ Pinball Party	Simpsons™ Pinball Party Technician Alerts
137	JUL 02, 2002	Austin Powers™	CPU Game ROM v3.01 Bug
136A	JUN 21, 2002	Playboy	U7 Sound ROM Update DOES NOT RESOLVE...
136	MAY 02, 2002	Playboy	Early Production U7 Sound ROM Change
135	MAY 01, 2002	Monopoly®	OPTIONAL MONOPOLY® Ramp Buty. Fix Kit
134	APR 11, 2002	Playboy >>Current	Difficulty in Playfield Glass Removal
133	APR 01, 2002	Monopoly® and Austin Powers™	...CPU/Sound Bd. Mod. : Low Volume Setting Hum
132	MAR 04, 2002	Playboy	Using Your Adjustable Outlane Posts
131	JAN 23, 2002	Monopoly®	Electric Co. Sign / Backbox J2 Harness Re-dress
130	DEC 10, 2001	Monopoly®	Tips & Tricks - The Water Works Rotating Flipper
129	OCT 22, 2001	Monopoly®	...Playfield Mylar, SPI P.N. 820-5094-00
128	SEP 25, 2001	Austin Powers™	...Code Update v3.00 CPU/Disp.: Add. of Adj. 60
127	SEP 19, 2001	Striker Xtreme & NFL™	Plastic Stadium Flashlamp Removal
126	SEP 19, 2001	Monopoly®>>Current	The Bubble Level is back!
125	APR 19, 2001	A13>>Current (White Star Bd. System)	Quick Tip for Display Troubleshooting
124	MAR 16, 2001	Sharkey's Shootout & H.R. Casino	Software Update: Replay Bug Fix for...
123	MAR 6, 2001	High Roller Casino	Ball Trap Fix @ Bottom Bumper
122	FEB 22, 2001	High Roller Casino	HRC Roulette Wheel (Top & Bottom) Assembly
121	FEB 5, 2001	Harley-Davidson®	... Plastic (Butyrate) -15 Support Plate Kit
120	DEC 29, 2000	Sharkey's Shootout	... Mystery Ball Mag. Fuse Fatigue: ...2.04 Update
119	NOV 8, 2000	General	P.P.M.I. - Pinball Preventative Maint. Inspection
118	AUG 21, 2000	Striker Xtreme & Sharkey's Shootout	Drop Target Replacement Procedure for...
117	JUN 13, 2000	General	Please Join our Service Bulletin eMail Distribution.
116	JUN 12, 2000	Titanic Redemption Game	Potential Revenue Loss
115	MAY 3, 2000	Striker Xtreme	Striker Xtreme Earnings
114	FEB 11, 2000	Harley-Davidson®	Operator Alert #19 - Motor Relay
113	DEC 10, 1999	Harley-Davidson®	H-D® Ball Guide... & Butyrate -16... Kit
112	JUN 7, 1999	A13 >> Current	CPU U218 & I/O U210 Pin-3 Removal
111	FEB 18, 1999	South Park	...8MB EPROM's for Expanded Speech & Sound
110	NOV 24, 1998	Space Jam >> Current	Modular Stand-Up Targets: a new way to order
109	SEP 30, 1998	Godzilla	...Manual Addendum: Flipper Coils
108	AUG 18, 1998	Prior << Batman Forever >> Current	"Sega" ... & "Data East" ... Flipper Rebuild Kits
107	AUG 13, 1998	All Games (General)	Fax Response Survey: How would you like your...
106	JUN 2, 1998	Multiple Games (See Bulletin for Games)	Large Dot Display Optional Enhancement Cable
105	NOV 21, 1997	The X-Files	...: Playfield Update Kit (500-6281-00)
104	SEP 25, 1997	Multiple Games (See Bulletin for Games)	Future Parts & Service Pinball...(Questionnaire)
103	JUL 14, 1997	Playboy thru Rocky & Bullwinkle	Solid State Flipper Bd. (Non-E.O.S.) conversion



Note: This Index is sorted with the latest bulletin at the top as in the binder. Hand write in space provided for new bulletins.

STERN PINBALL®SERVICE BULLETIN UPDATED INDEX 97 96 95 94 93

SB N°	DATE	GAME NAME(S)	SUBJECT OF BULLETIN
102	JUN 20, 1997	The Star Wars Trilogy - S.E.	FYI: What's New ("Y" Actuator Heavy Duty Sw.) ...
101	JUN 10, 1997	The Lost World: Jurassic Park.....	Important Unpacking Information.....
100	MAY 19, 1997	The Star Wars Trilogy - S.E.	Software CPU/Display Final Code Version
099	MAY 13, 1997	Multiple Games (See Bulletin for Games)...	FYI: Correct P/F Glass Dimensions...Wide Body...
098	APR 8, 1997	The Star Wars Trilogy - S.E.	Addition of Reset Align. Bracket Kit... ..
097	APR 8, 1997	The Star Wars Trilogy - S.E.	X-Wing Motor Bushing.....
96A	MAY 12, 1997	Space Jam >> Current.....	Dot Matrix Display Bd. 4X Spacer/2X Bracket.....
95A	APR 11, 1997	The Star Wars Trilogy - S.E.	...Reed Sw. Replacement Kit...& Procedure
094	MAR 3, 1997	Lethal Weapon 3 >> Current.....	Flipper Alignment Spots.....
093	JAN 27, 1997	Space Jam.....	FYI: ...problem in...I/O Power Driver Boards.....
092	DEC 5, 1996	Apollo 13 >> Current.....	FYI: MOSFETs in the White Star Bd. System
091	NOV 27, 1996	Twister	Magnet Processor Bd. & Disc Motor Updates
090	NOV 20, 1996	Space Jam >> Current.....	FYI: Sega Showcase Backbox.....
089	NOV 19, 1996	Apollo 13 >> Current.....	FYI: Switches.....
088	OCT 14, 1996	All Games (General)	Excerpt from Customer Fax.....
087	SEP 4, 1996	Laser War >> The Simpsons.....	FYI: Alphanumeric & 7-Segment Display Operation
086	SEP 3, 1996	Independance Day.....	Potential Balltrap in the Plastic Under-Trough.....
085	MAY 15, 1996	Twister >> Current.....	New 2-Flipper Theory of Operation & Schematic ...
084	MAR 5, 1996	Golden Eye	Fuse/Power Updates
083	JAN 23, 1996	Batman Forever	Premature Failure of the New Style Flipper Pawl ...
082	JAN 23, 1996	Apollo 13 >> Current.....	The New "White ☆ Star Board System"
081	JAN 9, 1996	Apollo 13.....	System Update
080	DEC 21, 1995	Apollo 13.....	Theory of Operation: P/F Mag. Infrface & 7-Seg.....
079	DEC 18, 1995	Apollo 13.....	5 Amp to 3 Amp Slo-Blo Fuse Change.....
078	OCT 2, 1995	Laser War >> Batman Forever	A handy little CPU troubleshooting gimmick.....
077	AUG 24, 1995	Current Games	"What is this pinball machine trying to tell me?"
076	AUG 23, 1995	Checkpoint >> Hook	Testing Sm. Dot Matrix (128X16)...Display Glass ...
075	AUG 22, 1995	All Games	CPU Board - Blanking Circuit Theory of Operation
074	APR 28, 1995	Baywatch	Modification to Early Production Games.....
073	APR 28, 1995	Baywatch & Batman Forever.....	New Portals™ Service Menu
072	FEB 17, 1995	Mary Shelley's Frankenstein	Creature: A Technical Overview
071	FEB 17, 1995	Maverick.....	Ball Trap
070	FEB 14, 1995	Mary Shelley's Frankenstein	Software Change Notice.....
069	FEB 14, 1995	Maverick.....	Software Change Notice.....
068	JAN 27, 1995	Frankenstein (+Games Hereafter)	New Service Feature: Bi-Directional Aud/Adj/Diaq .
067	JAN 19, 1995	Maverick.....	OPTO's A Technical Overview
066	NOV 2, 1994	The Who's Tommy	New Ball Kicker Arm Assembly.....
065	NOV 2, 1994	Maverick >> Baywatch	F.Y.I. Maverick Display 64 X 192 Dot Matrix Intro. ...
064	NOV 1, 1994	Guns N' Roses	Shooter Lane Ramp Mounting Modification.....
063	OCT 4, 1994	Guns N' Roses	Auto Launch Failures
062	AUG 22, 1994	All Games (Gen.) & Laser War >> Maverick	Coil Designation with Part Numbers
061	AUG 3, 1994	Wacky Gator (Redemption).....	Update Instructions.....
060	JUL 22, 1994	Guns N' Roses (+Games Hereafter)	New Design: Cabinet Legs/ Backbox Easy Access System.
059	MAY 27, 1994	The Who's Tommy	Servo Motor Stripping Gears
058	APR 15, 1994	Multiple Games (See Bulletin for Games)...	Solid State Flippers - Remains Energized
057	APR 8, 1994	Tales from the Crypt.....	Solid State Flipper Board.....
056	MAR 1, 1994	Multiple Games (See Bulletin for Games)...	Game Code Updates
055	FEB 28, 1994	Multiple Games (See Bulletin for Games)...	Game Resets.....
054	MAR 23, 1994	Multiple Games (See Bulletin for Games)...	Flipper / End of Stroke Failures
053	JAN 31, 1994	Jurassic Park.....	Common & Inherent Problems
052	DEC 16, 1993	Tales from the Crypt.....	PPB - L/R Relay Failure
051	JAN 17, 1994	Tales from the Crypt.....	Printer Interface Not Functional
050	NOV 16, 1993	Multiple Games (See Bulletin for Games)...	Dot Matrix Display Glass - Theory of Operation
049	NOV 16, 1993	Multiple Games (See Bulletin for Games)...	Solid State Flipper - Theory of Operation
048	NOV 12, 1993	Last Action Hero	Lock Ball Assembly.....
047	OCT 24, 1993	Jurassic Park.....	EPROM Rev. 5.10.....



Note: This Index is sorted with the latest bulletin at the top as in the binder. Hand write in space provided for new bulletins.

STERN PINBALL®SERVICE BULLETIN UPDATED INDEX 93 92 91 90 89 88

SB N°	DATE	GAME NAME(S)	SUBJECT OF BULLETIN
046	OCT 19, 1993	Jurassic Park.....	Flipper Return Springs.....
045	NOV 12, 1993	Tales from the Crypt.....	Captive Ball/Flat Rail Update
044	JUN 17, 1993	Jurassic Park.....	Flipper Return Springs (Ltd. Dist. by Serial #).....
043	JUN 17, 1993	Jurassic Park.....	Failure of Switch #37 Center Scoop
042	JUN 17, 1993	Jurassic Park.....	Left-Right Motor (Fails Prematurely)
041	JUN 17, 1993	Jurassic Park.....	Up-Down Motor (Fails Prematurely)
040	JUN 17, 1993	Jurassic Park.....	Weak Kick on Dino Saucer Eject
39A	JUN 17, 1993	Jurassic Park.....	T-Rex Theory of Operation
039	JUN 17, 1993	Jurassic Park.....	ROM Rev. 5.00 for Early Jurassic Park Games
38C	APR 2, 1993	Rocky & Bullwinkle & Friends	Ball Draining (Orbit Shot).....
38B	JAN 4, 1993	Star Wars	Display Controller EPROMS
38A	AUG 14, 1992	Leathal Weapon 3	Stealth Coating Maint.
038	AUG 14, 1992	Leathal Weapon 3	Type Error on P.S.
037	JUL 20, 1992	Hook.....	Erratic Play
36A	JUL 6, 1992	Leathal Weapon 3	Possible High Voltage Failures on Power Supply Bd..
036	JUL 20, 1992	Leathal Weapon 3	Flipper Adjustment.....
035	APR 16, 1992	Star Trek 25th Anniversary	Game Program
034	FEB 6, 1992	Star Trek 25th Anniversary	Chase Light Update
033	DEC 18, 1991	Star Trek 25th Anniversary	Transporter FX Theory of Operation
032	DEC 17, 1991	Star Trek 25th Anniversary	Ramp-Up Mechanism
031	DEC 6, 1991	Star Trek 25th Anniversary	Program Update
030	SEP 19, 1991	Batman.....	Shooter Lane Update.....
029	MAY 7, 1991	Checkpoint / Teenage Mutant Ninja Turtles ...	Wiring of Speaker
28A	FEB 20, 1991	Multiple Games (Checkpoint >> Present) ...	Modification to new P.S. Comp.
028	FEB 20, 1991	The Simpsons.....	Cooling Tower Breakage.....
027	OCT 23, 1990	The Simpsons	Ground Fault Problem.....
26A	SEP 5, 1990	Back to the Future.....	Program Error
026	SEP 4, 1990	Back to the Future.....	Program Update
025	MAY 8, 1990	Phantom of the Opera.....	Solid State Update.....
024	MAR 22, 1990	ABC Monday Night Football	Weak Ball Trough
023	JUN 29, 1990	Robocop.....	Solid State Update.....
022	DEC 7, 1989	ABC Monday Night Football	Q54 Failure
021	DEC 5, 1989	ABC Monday Night Football	Links on ABC Monday Night Football
020	DEC 4, 1989	All Games	Solenoid Failure
019	AUG 31, 1989	Secret Service	Slap Shot Updates.....
18A	JUL 14, 1989	Playboy 35th Anniversary	Ball Catch
018	JUN 12, 1989	Playboy 35th Anniversary	Program Revision
017	MAY 26, 1989	Playboy 35th Anniversary	Bulletin & Replay Level.....
16A	JAN 5, 1989	Time Machine	High Score Settings
016	MAY 26, 1989	Time Machine	Power Supply Modification.....
015	APR 6, 1989	Time Machine	Ramp Modification
014	APR 3, 1989	Laser War.....	CPU Update.....
013	SEP 9, 1988	Secret Service	Preventive Maintenance, E.O.S.
012	SEP 7, 1988	Secret Service	Fuse Change
011	JUN 16, 1988	Secret Service	Coil T.D. Chart
010	JUN 15, 1988	Secret Service	Ball Eater Adjustment
009	MAY 27, 1988	Secret Service	Flipper E.O.S. Actuator
008	MAY 12, 1988	Secret Service	Correction to Spinner Modification, SB 003.....
007	MAY 6, 1988	Secret Service	Flipper Assembly Change.....
006	APR 27, 1988	Secret Service & Laser War.....	CPU Board Changeability.....
005	APR 26, 1988	Secret Service	Up Post Adjustment
004	APR 25, 1988	Secret Service	Ball Trap Modification
003	APR 20, 1988	Laser War.....	Game Improvements
002	APR 18, 1988	Secret Service	Manual Correction
01A	APR 12, 1988	Secret Service	Cross Playfield Plunger Shot
001	APR 12, 1988	Secret Service	Ball Trap Modification